Field Manual
No 10-584
Technical Order
No 13C7-6-71

DEPARTMENTS OF THE ARMY
AND THE AIR FORCE
Washington, DC, 12 August 1983

AIRDROP OF SUPPLIES AND EQUIPMENT: RIGGING INDUSTRIAL WHEELED TRACTORS

TABLE OF CONTENTS

		Paragraph	Page
	LIST OF ILLUSTRATIONS		iii
CHAPTER 1	INTRODUCTION		
	Scope	1-1	1-1
	Special Considerations	1-2	1-1
	Recommended Changes	1-3	1-1
CHAPTER 2	RIGGING M-R-S 100MC INDUSTRIAL WHEELED TRACTOR FOR LOW-VELOCITY AIRDROP		
	Description of Load	2-1	2-1
	Preparing Platform	2-2	2-1
	Building and Placing Honeycomb Stacks	2-3	2-1
	Preparing Tractor	2-4	2-1
	Attaching Suspension Slings	2-5	2-6
	Setting Tractor on Platform	2-6	2-6
	Lashing Tractor	2-7	2-6
	Installing Load Cover	2-8	2-11
	Preparing Parachute Stowage Platform	2-9	2-11
	Stowing Cargo Parachutes	2-10	2-13
	Installing Extraction Force Transfer Coupling (EFTC)	2-11	2-14
	Installing Release System	2-12	2-16
	Forming the Emergency Restraint System	2-13	2-17
	Positioning Extraction Parachute	2-14	2-18
	Aircraft Loading Requirements	2-15	2-18
	Marking Rigged Load	2-16	2-18
	Equipment Required	2-17	2-19

*This manual supersedes FM 10-584/TO 13C7-6-71, 15 May 1975.

		Paragraph	Page
CHAPTER 3	RIGGING M-R-S 100MC INDUSTRIAL WHEELED TRACTOR FOR LAPE AIRDROP		
	[redacted]	3-1	3-1
		3-2	3-1
		3-3	3-1
		3-4	3-1
		3-5	3-6
		3-6	3-7
		3-7	3-7
		3-8	3-17
		3-9	3-18
		3-10	3-18
APPENDIX A	REFERENCES		A-1
GLOSSARY			GLOSSARY-1

VED: 95 MESSAGE TERMINATION OF

LIST OF ILLUSTRATIONS

Figure Number		Page
1-1	M-R-S 100MC industrial wheeled tractor	1-2
2-1	Platform prepared	2-2
2-2	Honeycomb stacks in place	2-3
2-3	Rear of tractor prepared	2-4
2-4	Light, exhaust stack, and steering wheel secured	2-5
2-5	Suspension slings attached and tractor set on platform	2-6
2-6	Lashings 1 through 18 installed	2-7
2-7	Lashings 19 through 30 installed	2-8
2-8	Lashings 31 through 34 installed	2-9
2-9	Weight transfer cylinder secured	2-10
2-10	Construction details for stowage platform	2-11
2-11	Parachute stowage platform positioned and secured	2-12
2-12	Cargo parachutes stowed	2-13
2-13	Release cable safetied	2-14
2-14	Latch assembly and extraction line installed	2-15
2-15	M-2 cargo parachute release installed	2-16
2-16	Emergency restraint system	2-17
2-17	M-R-S 100MC rigged for low-velocity airdrop	2-18
3-1	Platform prepared	3-2
3-2	Honeycomb placed on platform	3-3
3-3	Rear view of stack number 6	3-4
3-4	Weight transfer cylinder stowed	3-5
3-5	Exhaust extension and lights stowed	3-6
3-6	Tractor positioned on honeycomb stacks	3-7
3-7	Lashings 1 through 12 installed	3-8
3-8	Lashings 13 through 16 installed	3-9
3-9	Lashings 17 through 28 installed	3-10
3-10	Lashings 29 through 40 installed	3-11
3-11	Lashings 41 through 46 installed	3-12
3-12	Lashings 47 through 58 installed	3-13
3-13	Lashings 59 through 68 installed	3-14
3-14	Lashings 69 through 80 installed	3-15
3-15	Lashings 81 and 82 installed	3-16
3-16	Extraction system installed	3-17
3-17	M-R-S 100MC tractor rigged for LAPE airdrop	3-18