

***** UNCLASSIFIED//FOR OFFICIAL USE ONLY *****

Subject: Maintenance Action (MA) message, TACOM Life Cycle Management Command, (TACOM LCMC) Control No. MA 13-040 Split Ring Wheel Assembly Replacement

Models Affected: M149A2, MKT, M103A3, M200A1 Dual, M105A2, M313, M332, M348A2 series, M373A2, M390C, M447, M447C, M750, XM1005, XM1007, XM822E1, XM971, XM971E series, XM995, XM995E1, and XM995E2 trailers

REFERENCES: No previous Maintenance Messages are known for this equipment and stated Maintenance Issue.

1. Distribution:

This is a "Maintenance Action Message". Commanders / Directors of Army Commands (ACOM) / Army Service Component Commands (ASCC)/Direct Reporting Units (DRU), Army National Guard (ARNG), US Army Reserve (USAR) Command, US Navy (USN), US Air Force (USAF), US Marine Corps (USMC) and other Service Commanders and Responsible Offices will retransmit this message to all subordinate Commanders / Activities.

2. Compliance Reporting:

Compliance reporting is not required as a result of this Maintenance Advisory Message.

3. Message Library:

This message will be available on the Safety First Website located on the TACOM Unique Logistics Support Applications (TULSA) portal within twenty-four hours of transmission. Access to the Safety First Website requires CAC Card authentication. You must first request access to the Safety First Website. The website is <https://tulsa.tacom.army.mil>. For assistance, email the TULSA Helpdesk at usarmy.detroit.tacom.mbx.ilsc-tulsa@mail.mil. The Safety First Website also has the capability to email Safety and Maintenance messages directly to your inbox. To subscribe to the mailing list, click on, E-Mail Subscriptions, on the Navigation bar.

4. Issue:

The split ring wheel assemblies used on the models listed above will be replaced with a new wheel assembly (NSN 2530-01-611-7619). This new wheel assembly replaces all bias ply and radial tire/wheel assemblies.

5. User Actions:

a. Effective immediately, TACOM is only authorizing the use of this new single piece wheel assembly as a wheel assembly replacement. Previous wheel assemblies are not authorized.

b. Units with M149A2, MKT, M103A3, M200A1 Dual, M105A2, M313, M332, M348A2 series, M373A2, M390C, M447, M447C, M750, XM1005, XM1007, XM822E1, XM971, XM971E series, XM995, XM995E1, and XM995E2 trailers are to use wheel assembly, NSN 2530-01-611-7619 when replacing tires and / or wheel assemblies.

This new wheel assembly consists of:

Radial Tire (10.00R22.5)	NSN 2610-01-063-7947
Wheel Rim (Single Piece)	NSN 2640-01-588-9171
Valve Stem	NSN 2640-01-522-2413
Cap	NSN 2640-00-060-3550

c. Split ring wheel assemblies are only being replaced through attrition. Do not replace serviceable tires and wheel assemblies. Models identified in para 5c that have an unserviceable split rim assembly will have all tires/wheel assemblies replaced with the new wheel assembly or new wheel assembly components. Users are reminded to NOT mix bias ply and radial tires or split ring and solid wheel assemblies on the trailers and adhere to the tire inflation values for the trailer.

d. Wheel assembly 2530-01-611-7619 will not be available to requisition until first quarter FY14; prior to first quarter FY14 units will be required to assemble 2530-01-611-7619 using the down-parts listed in paragraph 5b. Refer to TM 9-2610-200-14 for assembly and disassembly of tire and wheels.

6. Unit Commanders:

Contact your local TACOM Logistics Assistance Representative (LAR) or your State Surface Maintenance Manager upon receipt of this message for assistance. For assistance in locating your TACOM LAR, see paragraph 9C.

7. TACOM / PM Actions:

The following Technical Manuals will be updated during the next TM revision or update: TM 9-2330-267-14&P; TM 10-7360-206-23P; TM 9-2330-213-14&P; TM 9-2330-205-14&P; TM 9-2330-246-24&P; TM 9-2330-235-14&P; TM 9-2330-238-24&P; TM 9-2330-362-14&P; TM 9-2330-363-14&P; TM 9-2330-373-14&P during the next TM revision or update.

8. Supply Status:

TACOM currently has procurement actions in place to support expected requirements. Wheel assembly NSN: 2530-01-611-7619 is expected during the first quarter of FY14.

9. POCs:

a. Maintenance System Manager, AMSTA-LCC-HT, DSN 786-1633, Commercial, (586) 282-1633.

b. Weapon System Manager, AMSTA-LCC-HT, DSN 786-6800, Commercial, (586) 282-6800.

c. To find your TACOM LCMC LAR, contact the TACOM LCMC Senior Command Representative (SCR) for your area.

(1) CONUS-East Region includes all Active Duty, National Guard and Reserve877959

Units in Wisconsin, Illinois, Michigan, Indiana, Ohio, Kentucky, Tennessee, Mississippi, Alabama, Georgia, Florida, Louisiana, South Carolina, North Carolina, Virginia, West Virginia, Maryland, Delaware, Pennsylvania, New Jersey, Connecticut, Rhode Island, Massachusetts, New York, New Hampshire, Vermont, Maine and FORSCOM. CONUS-East SCR can be reached at DSN 312-236-6921, Commercial 910-396-6921.

(2) CONUS-West Region includes all Active Duty, National Guard and Reserve Units in North Dakota, South Dakota, Minnesota, Nebraska, Iowa, Missouri, Kansas, Oklahoma, Arkansas, Texas, Colorado, Montana, and Wyoming. CONUS-West SCR can be reached at DSN 312-737-0263, Commercial 254-287-0263.

(3) Pacific Region includes all Active Duty, National Guard and Reserve Units in Washington, Oregon, Idaho, Nevada, Utah, Arizona, Alaska, Hawaii, California, New Mexico and Guam. Pacific SCR can be reached at DSN 312-357-2991, Commercial 253-967-2991.

(4) Europe Region includes all Active Duty, National Guard and Reserve Units in Great Britain, Germany, Belgium, Luxemburg, Italy, Bosnia, Kosovo, and Macedonia. Europe SCR can be reached at DSN 314-483-4090, Commercial 011-49-631-411-4090, in Germany, 0631-411-4090.

(5) Far East Region includes all Active Duty, National Guard and Reserve Units in Korea, Okinawa, Kwajalein, and Japan. Far East SCR can be reached at DSN 315-768-7943, commercial 011-82-53-470-7943.

(6) SWA - Kuwait includes all Active Duty, National Guard and Reserve Units in Kuwait. SWA - Kuwait SCR at Camp Arifjan can be reached at DSN 318-430-4189.

(7) SWA OEF Region (Afghanistan) SWA, Region OEF includes all Active Duty, National Guard and Reserve Units in Afghanistan. SWA Region 401st AFSB OEF SCR can be reached at DSN 318-481-4814.

(8) For US Special Operations Command contact, Special Operations Forces Support Activity (SOFSFA), DSN: 745-4302, Commercial 859-566-5632 or 859-566-5603.

Classification: UNCLASSIFIED
Caveats: FOUO