








TURN HOOK ARM PIN AROUND



NOT IF HE DOESN'T MOVE THAT HOOK ARM PIN, HE WON'T!

OPERATORS, THE REFRIGERATION CONDENSER UNITS IN THE MULTI-TEMPERATURE REFRIGERATED CONTAINER SYSTEM (MTRCS) ARE SUFFERING A LOT OF DAMAGE.

THAT'S BECAUSE THE HOOK ARM PIN ON THE M1074/A1 PLS AND M1120/A2/A4 HEMTT LHS CAN MOVE FREELY IN THE ARM.



PLS Trailer Wheel Rims Have 12 or 14 Bolts

By now, your unit's M1076 PLS trailers should no longer have 10-bolt wheel rims. That's true if MWO 9-2330-385-20-1, *Installation Instructions for Bolt Together Wheels*, has been applied. The MWO describes a 12-bolt rim (Titan wheel), but a 14-bolt rim (Accuride wheel) will work fine, too. Either wheel rim comes with NSN 2530-01-500-4991 and can be mixed on the same trailer and axle.